

RECEIVED

JUN 11 1987

DIVISION OF
OIL, GAS & MINING

DOE/037/032

June 11, 1987

Mr. Elvin Maxwell
Rural Route 1
Box 36
Fessenden, ND 58438

Dear Mr. Maxwell:

RE: Utah State Mineral Lease ML 29540 - Metalliferous Mineral

I recently visited lands covered by the above numbered mineral lease and discovered that you have failed to complete the reclamation measures which you agreed to and which were stipulated as part of the approval of your exploration drilling program for 1986. Drill holes were left unplugged, drill cuttings were not evenly distributed across the drill sites, and the drill sites were not reseeded adequately.

Please attend to these required reclamation measures as soon as possible and have the drill sites reseeded this fall in order for your lease to remain in good standing.

Thank you for your cooperation in this matter.

Sincerely,

JERRY W. MANSFIELD
MINERAL RESOURCES SPECIALIST

JWM/eb

✓ FRANK FILAS